

Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-2

Date: Mar 17, 2005

Direction of Photo: Looking south.

Description:

Site S. Southwestern portion of landfill on site looking south at typical methane vent in landfill.



Photo No. S-3

Date: Mar 17, 2005

Direction of Photo:

Looking northeast.

Description:

Site S. Southeastern portion of site looking northeast at typical methane collection box for landfill.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-4

Date: Mar 17, 2005

Direction of Photo:

Looking south.

Description:

Site S. Southeastern portion of site looking south at methane collection enclosure.



Photo No. S-5

Date: Mar 17, 2005

Direction of Photo:

Looking west.

Description:

Site S. Eastern portion of site looking west at methane collection pump.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-6

Date: Mar 22, 2005

Direction of Photo:

Looking west.

Description:

Site S. Northwest portion.
Typical series of wells near the landfill.



Photo No. S-7 **Date:** Mar 17, 2005

Direction of Photo:

Looking north.

Description:

Site S. Eastern portion of site.
Unused dumpsters being stored on site.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-8

Date: Mar 17, 2005

Direction of Photo:

Looking northwest.

Description:

Site S. North-central portion of site. Unused trailers in background and gravel pile to left of figure.



Photo No. S-9 A

Date: Apr 4, 2005

Direction of Photo: Looking north.

Description:

Site S. Old drum storage area. Drums appear to be upside down and apparently empty.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-10

Date: Mar 22, 2005

Direction of Photo:

Looking east.

Description:

Site S. Northwest section.
Sign at start of

Sign at start of archery range.



Photo No. S-11

Date: Mar 22, 2005

Direction of Photo:

Looking north.

Description:

Site S. Northwest section. Typical target area at archery range.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-12

Date: Mar 22, 2005

Direction of Photo: Looking east.

Description:

Site S. Training course in southern portion of site.




Photo No. S-13 **Date:** Mar 22, 2005

Direction of Photo:

Looking northwest.

Description:

Site S. Southern section. Target Shed 8. Old coal bin in right-center of photo.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-14

Apr 4, 2005

Date:

Direction of Photo:

Looking southeast.

Description:

Site S. Southern section. Inside Target Shed 4.



Photo No. Date: S-15 Apr 4.

Apr 4, 2005

Direction of Photo:

Looking southeast.

Description:

Site S. Southern section. Inside Target Shed 8.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-16

Date: Mar 22, 2005

Direction of Photo: Looking northwest.

Description:

Site S. Southern section. Old coal bin southeast of Target Shed 4.




Photo No. S-17

Date: Mar 22, 2005

Direction of Photo: Looking northwest.

Description:

Site S. Southern section. Old coal bin southeast of Target Shed 8.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-18 **Date:** Mar 22, 2005

Direction of Photo:

Looking southeast.

Description:

Site S. Southern section. Coal adjacent to old coal bin at Target Shed 4.



Photo No. S-19

Date: Mar 17, 2005

Direction of Photo:

Looking south.

Description:

Site S. Southwestern portion of site. Well and pump house for water supply for base. Well in foreground, pump house is brick building with grey metal doors in background. Target shed 4 is to the right in the background.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-20

Date: Mar 22, 2005

Direction of Photo:

Looking northwest.

Description:

Site S. Southern section. Metro Transit Police trailer.



Photo No. S-21

Date: Apr 4, 2005

Direction of Photo:

Looking west.

Description:

Site S. Southern section. Inside Metro Transit Police trailer.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-22

Date: Mar 17, 2005

Direction of Photo:

Looking east.



Site S. Eastern portion of site looking east at polemounted transformers. Blue "non-PCB containing" labels visible.



Photo No. Date: S-23

Mar 22, 2005

Direction of Photo:

Looking northeast.

Description:

Site S. Southwest section. Polemounted transformers next to target shed 8. Blue "non-PCB containing" tag visible on transformers.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-24

Date: Mar 17, 2005

Direction of Photo:

Looking northeast.

Description:

Site S. Northwestern portion of site. Beaver dam.



Photo No. S-25

Date: Mar 22, 2005

Direction of Photo:

Looking east.

Description:

Site S. Northern section. Looking down old railroad spur.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-26

Date: Mar 22, 2005

Direction of Photo:

Looking east.

Description:

Site S. Northern section. View of a former railroad loading dock on top of the old railroad grade.



Photo No. S-27

Date: Mar 22, 2005

Direction of Photo: Looking southwest.

Description:

Site S. Northwest section. Old foundation.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-28

Date: Mar 22, 2005

Direction of Photo: Looking south.

Description:

Site S. Northwest section. View of an old building foundation.



Photo No. S-29

Date: Mar 22, 2005

Direction of Photo: Looking southwest.

Description:

Site S. Foundation in northwestern section of site may have been a scale for weighing vehicles entering landfill area.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-30

Date: Mar 22, 2005

Direction of Photo:

Looking east.

Description:

Site S. Northern section. View of an unidentified, concrete trough-like structure with a slope on one end.



Photo No. S-31

Date: Mar 22, 2005

Direction of Photo:

Looking northeast.

Description:

Site S. Southern section. Old foundation near current pole-mounted transformers near Target Shed 8.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-32

Date: Mar 22, 2005

Direction of Photo: Looking from above.

Description:

Site S. Southern section. Holes in old foundation, could have been conduits for wires if foundation was for a transformer.




Photo No. S-33

Date: Mar 22, 2005

Direction of Photo: Looking northwest.

Description:

Site S. Southern section. Water and sanitary sewer access adjacent to old foundation with pipes. Target Shed 8 is in background.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-34

Date: Mar 17, 2005

Direction of Photo: Looking west.

Description:

Site S. Southeastern portion of landfill looking west at abandoned washing machine outside fenced-in portion of landfill.



Photo No. S-35

Date: Mar 17, 2005

Direction of Photo: Looking northeast.

Description:

Site S. Southern portion of site. Office/household trash on ground. Location not far from Metro Transit Police trailer and Target Shed 4.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-36

Date: Mar 22, 2005

Direction of Photo: Looking south.

Description:

Site S. Northeast section. View of an old car that has been dumped in the northeast corner of the site.



Photo No. S-37

Date: Mar 22, 2005

Direction of Photo: Looking north.

Description:

Site S. Northeast section. View of an old refrigerator and scrap metal that has been dumped in the northeast corner of the site just south of the residences. Nearby, other items that have been dumped are a washing machine, stove, tires, and tarps.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-38

Date: Mar 22, 2005

Direction of Photo: Looking south.

Description:

Site S. North-central section. Sheen on water in marshy area. This section was near a break in the fence and downhill of the drum storage area.



Photo No. S-39

Date: Mar 22, 2005

Direction of Photo: Looking southwest.

Description:

Site S. North-central section showing break in fence around landfill. Landfill to the left of photo. Drum storage area behind trees to left of photo. Sheen on water in foreground.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-40

Date: Mar 22, 2005

Direction of Photo:

Looking eastnortheast.

Description:

Site S. Eastern section. View of two headstones in the Phelps cemetery. There are remains of two other headstones to the left.



Photo No. S-41


Date: Mar 17, 2005

Direction of Photo:

Looking north.

Description:

Site S. Target Shed 49 located west of site. Cardboard backing for targets stored inside.





Client Name: Fort Meade

Site Location:

Fort Meade EBS for EUL

Project No. 15296957

Photo No. S-42

Date: Mar 17, 2005

Direction of Photo:

Looking southeast.

Description:

Site S. Fire Training Area located west of site.



Photo No. S-43

Date: Mar 17, 2005

Direction of Photo:

Looking southeast.

Description:

Site S. Northwestern portion of site. Fire Training Area to upper right of photo. Pole mounted transformer on pole in upper right of photo.

